



**Public Service Electric and Gas  
of New Jersey Selects Fox Industries, Inc.'s  
FX-70® System to Restore H-pile Supports**

**Problem:** Wet and dry cycles deteriorated steel causing severe section loss in 14x73 HP supporting gas line over the D&R canal.



**Solution:** The deteriorated section of H-pile was bridged using steel channel. Structurally restored pile is permanently protected with FX-70® Inert Corrosion Free System without any disruption in service. The FX-70 System consists of a stay-in-place FRP jacket, a bottom seal of FX-70-6 Pourable Epoxy Grout, and filled with FX-70-8® Underwater Mortar.